



ATTENTION GENERAL CONTRACTORS AND DESIGNERS:

O.R. CEILING CONSTRUCTION: FROM TURF WARS TO TEAMWORK

Building an OR ceiling involves more trades than just about any other part of a hospital's construction, and it all occurs in a tightly-packed space. Ensuring fit and function with ductwork, booms, structural, lights, conduit, med-gas, sprinklers, data lines, speakers, intercoms, and finishes...what could possibly go wrong? That's where Precision Air comes in.

YOUR CONFLICT-PREVENTION SPECIALIST

With over 50 years of OR airflow design and construction experience, we've seen it all. Our engineers are expertly trained to foresee and prevent the costly conflicts, turf wars and RFIs that are so common in OR ceiling construction. That's why your life will be so much easier when we're involved. We complement your project management by providing a coordinated, comprehensive road map ahead of time, helping you avoid the chaos that comes with multiple trades working independently.

LEVERAGING OUR
CROSS-DISCIPLINE EXPERTISE
MAKES YOUR LIFE A LOT LESS
STRESSFUL.

No more budget-breaking surprises



No more costly delays



No more surprise conflicts and RFIs



No more turf wars

LET US HELP YOU AVOID CONFLICTS LIKE THESE



PROBLEM: Ceiling cobbled together with makeshift pieces visible from the OR.

CAUSE: Installers “just making it work.”



PROBLEM: Expensive, time consuming, and chaotic looking patchwork of components.

CAUSE: Thinking “this is the way we’ve always done it.”



PROBLEM: Medical equipment obscuring diffusers. Filter access requires disassembly of all attached equipment.

CAUSE: Inexperienced mechanical designer placing diffusers over medical equipment.



PROBLEM: Difficult to access light and unprofessional appearance.

CAUSE: Lack of coordination between ceiling designer and medical equipment.



PROBLEM: Gap between framing allowing dirty air into room.

CAUSE: Lack of understanding of structural Unistrut integration and airflow.



PROBLEM: Boom overlap on framing leaves large gap for contaminants to leak into room from above the ceiling. Unprofessional appearance.

CAUSE: Result of ceiling system not being coordinated with boom details.

“There is no risk in buying from Precision Air.”

— GENERAL CONTRACTOR, VA AREA

“We didn’t have a single RFI (request for information).”

— ARCHITECT, VA AREA

“Nobody else is so proactive at catching conflicts between all the trades and guidelines.”

— MECHANICAL ENGINEER, CHICAGO AREA

“The end result is so perfect that it’s worth it every time.”

— MECHANICAL ENGINEER, PITTSBURGH AREA

You’ve never known what it’s like to work with such a proactive and complete partner. Try a project with us and see for yourself.

BREATHE EASY.

Help is just a phone call away.

(800) 404-0931

 **Precision Air** *The O.R. AirCare Specialists*

Precision Air Products Co.

7620 W. 78th Street, Bloomington MN 55439

precisionairproducts.com